

PPE CATEGORY LEVEL CHART NFPA 2009

CATEGORY 0

What Personal Protection Equipment (PPE) You Shall Wear:

- [X] Cotton Undergarments
- [X] Long Sleeved Shirt (Natural Fiber)
- [X] Long Pants (Natural Fiber)
- [X] Safety Glasses or Goggles
- [X] Hearing Protection (Inserts)
- [X] Leather Gloves (as needed) or Insulating Gloves w/Protectors



CATEGORY 1

What Personal Protection Equipment (PPE) You Shall Wear:

- [X] Cotton Undergarments
- [X] Arc Rated Long Sleeved Shirt (or FR Coveralls)
- [X] Arc Rated Long Pants (or FR Coveralls)
- [X] Hard Hat with Arc Rated Face Shield
- [X] Hearing Protection (Inserts)
- [X] Safety Glasses or Goggles
- [X] Leather Gloves or Insulating Gloves w/Protectors
- [X] Leather Shoes (as needed)



CATEGORY 2

What Personal Protection Equipment (PPE) You Shall Wear:

- [X] Cotton Undergarments
- [X] Short Sleeved "T" Shirt (Natural Fiber)
- [X] Arc Rated Long Sleeved Shirt and Long Pants or Arc Rated Coveralls instead
- [X] Hard Hat with Arc Rated Face Shield w/Sock Balaclava
- [X] Safety Glasses or Goggles
- [X] Hearing Protection (Inserts)
- [X] Leather Gloves or Insulating Gloves w/Protectors
- [X] Leather Shoes (as needed)



CATEGORY 3

What Personal Protection Equipment (PPE) You Shall Wear:

- [X] Cotton Underwear
- [X] Short Sleeved "T" Shirt (Natural Fiber)
- [X] Arc Rated Long Sleeved Shirt and Long Pants
- [X] Arc Rated Coveralls (Over the above)
- [X] Arc Rated (25 cal) Arc Flash Suit Jacket
- [X] Arc Rated (25 cal) Arc Flash Suit Pants
- [X] Arc Rated (25cal) Arc Flash Suite Hood
- [X] Hard Hat
- [X] Safety Glasses or Goggles
- [X] Hearing Protection
- [X] Arc Rated Leather Gloves or Insulating Gloves w/Protectors
- [X] Leather Shoes



CATEGORY 4

What Personal Protection Equipment (PPE) You Shall Wear:

- [X] Cotton Underwear
- [X] Short Sleeved "T" Shirt (Natural Fiber)
- [X] Arc Rated Long Sleeved Shirt and Long Pants
- [X] Arc Rated Coveralls (Over the above)
- [X] Arc Rated (40 cal) Arc Flash Suit Jacket
- [X] Arc Rated (40 cal) Arc Flash Suit Pants
- [X] Arc Rated (40 cal) Arc Flash Suite Hood
- [X] Hard Hat
- [X] Safety Glasses or Goggles
- [X] Hearing Protection
- [X] Arc Rated Leather Gloves or Insulating Gloves w/Protectors
- [X] Leather Shoes



Always wear voltage rated rubber glove liners when working above 50 volts in all categories!

COURTESY OF...



ARC FLASHwear

PUTTING ELECTRICAL SAFETY FIRST

WWW.OELSALES.COM

1-800-818-2244

FULL RANGE OF ELECTRIC PROTECTIVE CLOTHING